

**Illinois Commerce Commission
Pipeline Safety
Field Trip Report**

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Exit Meeting Contact: (Not Applicable)	Total Man Days: 0
Pipeline Safety Representative(s): Matt Smith	
Company Representative to Receive Report: Michael Fuller Company Representative's Email Address: mfuller2@ameren.com	<u>Emailed Date:</u> 12/26/2012

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Compliance Follow-Up	ICC Office	Matt Smith	Springfield	0	12/17/2012	N/A

Statement of Activities

Staff reviewed Ameren's response letter, including requested additional response information, to determine if the information was adequate to clear the NOPV. The review has determined the response information was adequate.

ISSUE(S) FOUND:

NO ISSUES FOUND.

ISSUE(S) CORRECTED:

NO ISSUES CORRECTED.

NOTICE OF AMENDMENT(S) FOUND:

NO NOAs FOUND.

NOA(S) CORRECTED:

NO NOAs CORRECTED.

NOTICE OF PROBABLE VIOLATION(S) FOUND:

NO NOPVs FOUND.

NOPV(S) CORRECTED:

2012-V1-00081 - Ameren will conduct a review of the entire Springfield operating center to determine if all locations that contain a single test point are adequate. Any location that is determined to be inadequate will require further action. Once the review is complete of the Ameren Springfield operating center then Ameren will determine if other locations within Ameren Illinois require similar test.